

# Hyundai R140-9



**£POA**

Hyundai R140-9

Year 2011

Hours 5800

Undercarriage 60-70% good

**Product Details**

Product Details	
<b>Category/Type</b>	<b>Excavators</b>
<b>Make</b>	<b>Hyundai</b>
<b>Model</b>	<b>R140-9</b>
<b>Year</b>	<b>2011</b>
<b>Hours</b>	<b>5800</b>

Hammer piped

Ennis Road, Ennistymon, County Clare, Ireland

Tel: +353 (0)87 935 9694

www.europlantandmachinerysales.com europlantandmachinerysales@gmail.com